

Vitellaro, Chandra

From: Tom Madsen <tommadsen15@gmail.com>
Sent: Friday, June 02, 2017 9:20 AM
To: Anderson-Carnahan, Linda; Bachman, Brenda; Carr, Nicholas; Walker, Michelle CIV USARMY CENWS (US)
Subject: Changes at Snow and Salmon Creek delta, winter 2017
Attachments: Snow Creek cutting banks in Salmon slough.JPG; Snow Creek Flowing into Salmon near Bud's.JPG; new leaching at Salmon Creek slough near Buds Tirecap..JPG; Excavated Rail Road Berm- Leaching winter 2017 (2).JPG; Grey Sediments in Snow Creek Channel near Bud's Tirecap.JPG

--

In a previous email the course change of Snow creek was discussed here are a few more photos. The sediments are mostly grey and there are areas of dead vegetation that look as if some agent in the leaching is killing it. The areas of dead and burnt vegetation first appeared in the fall of 2016 when the higher winter tides started. The affected vegetation turned black on exposure and did not recover this year.

Tom Madsen

Port Discovery Seafarms

(360) 301-6868 (cell)

(360) 385-4808 (home)

2915 SR 20, Port Townsend, WA 98368